

TPC 3D




Scanner Calibration Procedure


Intraoral Scanner User Guide

Everyone with a healthy and beautiful smile

1. Open any scan case and launch the scanning program in the Aidite intraoral scanner software.
2. Click the Calibration button in the upper right corner.



1. Complete calibration following the on-screen prompts.



Notes: If a "Calibration Successful" message appears after capturing Head A and Head C, you may skip the remaining calibration steps. Calibration heads are not interchangeable between different scanners. Calibration tip:

